
Henrico Training Center Stream Restoration Project



Henrico Training Center Stream Restoration Project

Deep Bank Erosion

Large amounts of Sediment Transport

Exposed Sanitary Sewer

Before




After



Before



After




Preparing Stream for Restoration



Regrading Stream & Installing Stream Structures



Stabilizing Floodplain



After Restoration

